

# 03 October 1997 Weight & Balance Data from Airframe Logbook

DATE 19__	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
				<p style="text-align: center;">I CERTIFY THAT THIS <u>ACFT</u> HAS BEEN INSPECTED ON <u>10/3/97</u> WITH TOTAL  <del>TACH</del> HOURS OF <u>4655</u> AND FOUND TO BE IN AIRWORTHY CONDITION IN ACCORDANCE WITH  <u>A BIENNIAL</u> INSPECTION ACCOMPLISHED PER FEDERAL AVIATION REGULATIONS PART 43</p> <p style="text-align: center;">SIGNED <u>Frank M. Taylor</u> AWP NO <u>283093257/A</u></p>
10-3-97				<p>REMOVED FROM A/C THE FOLLOWING EQUIP:</p> <p>1 - COLLINS ADF REC PT# 622-4480 001 SER# 2859</p> <p>1 - " INDICATOR PART# 622-2091 001 SER# 2859</p> <p>1 APPLLO LORAN MODEL 602 PART# 430-9801-001 SER# 24381</p> <p style="text-align: center;">NEW WT &amp; BAL FOLLOW:</p>

DATE 19__	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)																								
				<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 33%;"></td> <td style="width: 33%; text-align: center;">WT</td> <td style="width: 33%; text-align: center;">ARM</td> <td style="width: 33%; text-align: center;">MOMENT</td> </tr> <tr> <td>EMPTY WT</td> <td style="text-align: center;">1512.0</td> <td style="text-align: center;">39.0</td> <td style="text-align: center;">58968.00</td> </tr> <tr> <td>COLLINS ADF</td> <td style="text-align: center;">- 3.68</td> <td style="text-align: center;">10.9</td> <td style="text-align: center;">- 40.11</td> </tr> <tr> <td>INDICATOR</td> <td style="text-align: center;"><del>3.68</del></td> <td></td> <td></td> </tr> <tr> <td>APPLLO LORAN</td> <td style="text-align: center;">- 3.68</td> <td style="text-align: center;">10.9</td> <td style="text-align: center;">- 40.11</td> </tr> <tr> <td></td> <td style="text-align: center; border-top: 1px solid black;">1504.44</td> <td style="text-align: center; border-top: 1px solid black;">39.13</td> <td style="text-align: center; border-top: 1px solid black;">58887.78</td> </tr> </table>		WT	ARM	MOMENT	EMPTY WT	1512.0	39.0	58968.00	COLLINS ADF	- 3.68	10.9	- 40.11	INDICATOR	<del>3.68</del>			APPLLO LORAN	- 3.68	10.9	- 40.11		1504.44	39.13	58887.78
	WT	ARM	MOMENT																									
EMPTY WT	1512.0	39.0	58968.00																									
COLLINS ADF	- 3.68	10.9	- 40.11																									
INDICATOR	<del>3.68</del>																											
APPLLO LORAN	- 3.68	10.9	- 40.11																									
	1504.44	39.13	58887.78																									
				<p style="text-align: center;">NEW EMPTY WT</p> <p style="text-align: right; font-size: 1.2em;">John Wickham AWP 479448494</p>																								